

# CITY OF STILLWATER ARCHITECTURE- HISTORY INVENTORY FORM

Historic Name: House

Address: 503 North 4th Street

Current Owner:

Inventory No. WA-SWC-419

County: Washington

PIN: 10690-3200

City/Township: Stillwater

Review/Compliance No:

Township: T30N Range: R20W, Section 28 (SW 1/4 NE 1/4)

U.S.G.S. Quad Map: Stillwater, Minn-Wisc., 1967, photorevised 1980

U.T.M.: 15 514840 4989370

Architect/Contractor:

Style: Greek Revival

Date Built: 1856 Pre-1888 (S)

Photo Number(s): Roll 012534

Frame(s) 18

Survey Name: Stillwater North Hill (Original Town) Survey: HRI File #1369

Form prepared by: Norene Roberts, Historical Research Inc.

Date Surveyed: February-May, 1995

**Physical Description:** This Greek Revival-style residence has an attached garage in the rear and a side porch fronting West Cherry Street. The address of the house was originally 102 E. Cherry on the 1888 Sanborn map. The west facade is now the front facing N. 4th Street. Windows are 6-over-6 and 1-over-1 and are not original. The metal siding has destroyed much of the charm of this house, but the massing and proportions are good.

**Significance:** This house is \_\_\_\_ is not X preliminarily eligible to the National Register of Historic Places. This study is a preliminary determination because it is the first of the Stillwater neighborhoods to be surveyed.

**Statewide Historic Contexts:** St. Croix Triangle Lumbering, 1843 -1914; Early Agriculture and River Settlement, 1840-1870.

**Local Historic Context:** Development of Residential Neighborhoods in Stillwater, 1850s-1940s.

**National Register Eligible (prelim.):** \_\_\_\_ Yes X No \_\_\_\_ Insufficient Information

**Date listed on the National Register:**

CITY OF STILLWATER ARCHITECTURE-HISTORY CONTINUATION SHEET, PAGE 2

Address: 503 North 4th Street

Inventory No. WA-SWC-419

Present Use: Residential, single family

Zoning District: RB-2 family residential

Integrity:

Condition:

Excellent

Excellent

Good

Good

Fair

Fair

Poor

Poor

Stories: 1 1/2

Roof style or shape: Gabled; standing seam metal

Structural System: Wood-framed

Windows: 6-over-6 and 1-over-1 (not original)

Foundation: Concrete skim coat; underlying material not visible

Wall Treatment: Metal siding

Alterations: New fluted front entrance columns; new windows, metal siding, attached garage on north.

Legal Description: Original Town, Block      Lot

Historic Information:

Sources:

Open to the public:       Yes       No       Limited