

CITY OF STILLWATER ARCHITECTURAL-HISTORY Continuation Sheet, Page 2

Address: 437 South Broadway Street

Inventory No.: WA-SWC- 007

Present Use: residential, single family

Zoning District:

Integrity: _____ Excellent
_____ Good
 X Fair
_____ Poor

Condition: _____ Excellent
 X Good
_____ Fair
_____ Poor

Stories: 2

Roof style/shape: hipped

Structural System: wood frame

Windows: 1-over-1, picture window

Foundation: stone

Wall Treatment: weatherboard

Alterations: modified front portico and picture window addition, aluminum storm windows

Legal Description: Plat

Block

Lot

Historic Information:

Plaque reads: "1858 A.D."

Sources:

Shown on the 1870 Ruger view
Rollins, ca.1976

Open to the public: _____ Yes X No _____ Limited